

Comunicazione tecnica n°: **25/10**  
Technical communication n°: **25/10**

data/date: **01/10/2025**

Riferimento modello/i: EASY 6000 PRO  
Machine/s kind: EASY 6000 PRO

Oggetto: Nuova release firmware V.0.19 per scheda Mainboard 082672  
Subject: New firmware release V.0.19 for 082672 Mainboard

Con la presente si informa che è disponibile la nuova versione firmware per la scheda Main 082672 dei distributori EASY 6000 PRO con tablet da 10" con i seguenti dati identificativi:

➤ **082672\_EASY6000\_PRO\_34DC\_V019**      **checksum 34DC**      **V.0.19**

Per il corretto funzionamento si consiglia di aggiornare anche Interfaccia e Motore (Engine "mytouchb"), aggiornabili da remoto.

Questa release si differenzia dalla versione 0.16 per:

- Migliorata la gestione firmware sul posizionamento e rotazione dischi evitando eventuali blocchi.
- Corretto errore sull'abilitazione dell'inibizione macchina.
- Aggiunta la possibilità di interrompere la transazione aperta in ALWAYS IDLE tramite opzione selezionabile sul tablet.

È stata aggiunta una pagina all'interfaccia che invita l'utente a procedere con il pagamento o annullare la transazione.

- Corretto eventuale errore di posizionamento disco durante la ricarica intelligente.
- Aggiunto nel file di log lo stato degli scomparti (pieni=1, vuoti=0, scaduti=2).
- Aggiunta gestione protettore termico resistenze sportelli.

Distinti Saluti  
FAS International S.p.A.

---

*Please be informed that a new firmware release for 082672 Main board of EASY 6000 PRO 10" tablet vending machine is now available, with the following identification data:*

➤ **082672\_EASY6000\_PRO\_34DC\_V019**                      **checksum 34DC**      **V.0.19**

*For correct operation, it is recommended to also update the Interface and Engine (Engine "mytouchb"), which can be updated remotely.*

*This release is different from the version 0.16 for:*

- Improved firmware management for disk positioning and rotation, preventing possible blocks.
- Fixed an error when enabling machine inhibition.
- Added the possibility to interrupt an open transaction in ALWAYS IDLE mode via a selectable option on the tablet.  
A page has been added to the interface prompting the user to proceed with the payment or cancel the transaction.
- Fixed a possible disk positioning error during intelligent refilling mode.
- Added the status of the compartments to the log file (full=1, empty=0, expired=2).
- Added management of the door heating element thermal protector.

*Kind Regard*  
*FAS International S.p.A.*